



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
06/13/2006

Supervisor 1027

Mine Name: Honey Onyx

Operator Name:

Russell C. Feller

688 E Chad Ranch Road

Veyo, Ut 84782-4141

Inspector(s): Tom Munson

Other Participants: none

Mine Status: Inactive

Permit number: S/023/027

Inspection Date: 05/09/2006

Time: 9:00AM

Weather: Sunny

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

To perform an annual Inspection.

Inspection Summary:

The site has been mined for many years but more recently it appears a new area was opened up and then regraded but not seeded as no vegetation was observed.

Conclusions and Recommendations:

The site needs to be scarified and seeded this fall in areas where mining has occurred.

Inspector's Signature

Thomas Munson

Date:

6/19/06

Directions to Site:

West of Nephi, Utah

TM:jb

cc: Russell Feller
Sitla, John Blake

Attachment: Photos

O:\M023-Juab\S0230027-Honeyonyx\inspections\inspection06132006.doc

HONEY ONLYX A+R LEASING



NEW DISTURBANCE - NEEDS REVEG.



HONEY OWL X
ATR LEASING





HOWEY ONLY X
A+R LEASING

← OLD PIT
↓

